



Federal Aviation Administration

A0579/26 NOTAMN

Q) NNTT/QRDCA/IV/BO/W/000/999/2843S12112W110

A) NNTT

B) 2605132348 C) 2605200303

D) 13 2348-0426, 14 2334-0412, 15 2320-0358, 16 2306-0344, 17
2252-0330, 18 2238-0316, 19 2225-0303

E) TEMPORAY DANGEROUS AREA DUE TO SPACE DEBRIS REENTRY OF SPACEX
NROL-172 IN TAHITI FIR WITHIN AN AREA BOUNDED BY THE FOLLOWING
COORDINATES:

3000S 12153W, 2759S 12244W, 2709S 12043W, 2843S 12000W, 3000S
12000W, 3000S 12153W,

THIS ACTIVITY ALSO AFFECTS SCIZ FIR.

THE FRENCH VERSION OF THIS NOTAM IS C1049/26

F) SFC G) UNL

-----End of PDF Report.-----