



Federal Aviation Administration

A0587/26 NOTAMN

Q) NTTT/QRDCA/IV/BO/W/000/999/2843S12112W110

A) NTTT

B) 2605120015 C) 2605180330

D) 12 0015-0453, 13 0002-0440, 13 2348-0426, 14 2334-0412,

15 2320-0358, 16 2306-0344, 17 2252-0330

E) TEMPORAY DANGEROUS AREA DUE TO SPACE DEBRIS REENTRY OF SPACEX
NROL-172 IN TAHITI FIR WITHIN AN AREA BOUNDED BY THE FOLLOWING

COORDINATES:

3000S 12153W, 2759S 12244W, 2709S 12043W, 2843S 12000W, 3000S

12000W, 3000S 12153W,

THIS ACTIVITY ALSO AFFECTS SCIZ FIR.

THE FRENCH VERSION OF THIS NOTAM IS C1061/26.

F) SFC G) UNL

-----End of PDF Report.-----